



11106 Xavier Court  
Minneapolis  
MN  
USA

---

## Image Report

**Claim Id**

Your Company Name

**Date of Loss**

Oct 15, 2025

**Date Claim Created**

Oct 16, 2025

**Type of Loss**

Vandalism

**Address**

123 ABC St, Columbia Heights, MN,  
USA

**Policyholder Name**

John Doe

---

# Table of Contents

<b>Main Building</b>	<b>3</b>
Exterior . . . . .	3
Overview Photos . . . . .	3
Room Notes . . . . .	6
Living Room . . . . .	7
Overview Photos . . . . .	7
Room Notes . . . . .	10
Kitchen . . . . .	10
Overview Photos . . . . .	10
Room Notes . . . . .	12
Hallway . . . . .	12
Overview Photos . . . . .	12
Room Notes . . . . .	13
Bathroom . . . . .	13
Overview Photos . . . . .	13
Room Notes . . . . .	14
Sketch . . . . .	15
Overview Photos . . . . .	15

---






**Structure: Main Building**






---







**Main Building: Exterior**

---

**Overview Photos: Exterior**









## Room Notes: Exterior

### Scope Notes

I took images of all elevations but only observed damage to the front.

Bullets through:

Front Door

2 hits to the stucco siding between the front door and window and one hit to the Upper left of the window

Window and glass had multiple hits.

Aluminum Siding

and Fascia

---

## Main Building: Living Room

---

### Overview Photos: Living Room













Photo 10 9:10 AM CDT Oct 17, 2025




Photo 11 9:10 AM CDT Oct 17, 2025




Photo 12 9:10 AM CDT Oct 17, 2025



Photo 13 9:10 AM CDT Oct 17, 2025




Photo 14 9:10 AM CDT Oct 17, 2025




Photo 15 9:10 AM CDT Oct 17, 2025



Photo 16 9:11 AM CDT Oct 17, 2025




Photo 17 9:11 AM CDT Oct 17, 2025




Photo 18 9:11 AM CDT Oct 17, 2025









Photo 19 9:11 AM CDT Oct 17, 2025





Photo 20 9:11 AM CDT Oct 17, 2025



Photo 21 9:11 AM CDT Oct 17, 2025








## Room Notes: Living Room

Scope
7 patches on drywall
1 damaged picture frame
Curtains damaged
Glass on carpet continuous to the hallway
Content manipulation 1-2 hours

## Main Building: Kitchen

### Overview Photos: Kitchen






Photo 4 9:13 AM CDT Oct 17, 2025



Photo 5 9:13 AM CDT Oct 17, 2025



Photo 6 9:13 AM CDT Oct 17, 2025



Photo 7 9:13 AM CDT Oct 17, 2025




Photo 8 9:13 AM CDT Oct 17, 2025



Photo 9 9:13 AM CDT Oct 17, 2025



Photo 10 9:13 AM CDT Oct 17, 2025




Photo 11 9:13 AM CDT Oct 17, 2025




Photo 12 9:13 AM CDT Oct 17, 2025




Photo 13 9:13 AM CDT Oct 17, 2025



Photo 14 10:05 AM CDT Oct 20, 2025

---

## Room Notes: Kitchen







Scope
Damage to cabinets
9 drywall patches
Paint room
content manipulation 2 hours


---

## Main Building: Hallway

---

### Overview Photos: Hallway











**Room Notes: Hallway**

Scope
Dry patch job
Paint room

**Main Building: Bathroom**

**Overview Photos: Bathroom**





## Room Notes: Bathroom

### Scope

Drywall patch  
paint  
content manipulation

